

## Merkland Fish Barrier

Deep ravine and waterfall immediately below outfall location is a barrier to upstream fish movement. Most of the depleted reach consists of these ravines with large water falls either end.



Outfall location

Rock shown in both images for reference



Ravine 3m – 4m deep. No safe way of measuring exactly.

Fall is vertical from immediately below outfall location.

Photos from along depleted reach:







